ALTERATIONS AND DISABILITY MODIFICATIONS POLICY

The co-operative's policies relating to alterations and disability modifications are detailed below in extracts from the current version of the Member Manual:

5. Liveability Property Modifications

5.1 SouthEast is committed to enhancing the liveability conditions for its members as their needs change over time as SouthEast is committed to supporting independent living by members in properties owned and managed by SouthEast. The SouthEast philosophy is to provide secure housing for members, if at all practicable and within a budget allocation. If a household includes a physically disabled child or adult, then in some instances an agreement could be reached regarding the provision of disability modifications. SouthEast, however, is not responsible for picking-up the cost of disability modifications.

This commitment is subject to the following:

- 5.2 SouthEast is primarily housing co-operative. Under the Residential Tenancies Act SouthEast is not obliged to provide property modifications because of new and/or emerging disability needs of members.
- 5.3 There being a liveability allocation in the budget.

5.4 Process

- 5.4.1 The tenant/member is responsible for obtaining an appropriate specialist assessment of the property, but in the case of a minor modification e.g. not structural, a written recommendation from a specialist medical practitioner may be sufficient.
- 5.4.2 With the assistance of the appropriate specialist the tenant/member should seek funding from appropriate authorities e.g. Veteran Affairs; the local council/shire; Vision Australia; home & community services or other agencies; child funding packages, Human Services; etc.
- 5.4.3 Before the next step is taken, agreement needs to be reached between SouthEast, the tenant/member, the appropriate specialist and the funding body/bodies in order to determine what needs to be done and who will be financially responsible. SouthEast may not have the funds and funds provided will be subject to the SouthEast budget. SouthEast can only provide funding within limits of the budget.
- 5.4.4 SouthEast may recommend that the tenant/member consider options for relocating to a more appropriate house/unit. Owned and/or managed by SouthEast

5.5 Minor modifications which SouthEast will permit subject to budget allocation:

- grab rails; hand rails; hand held shower sets; fold-down shower sets;
- re-location/replacement of door handles and locks;
- lever or capstand handled taps;
- thermostatically controlled hot water system to bathroom only;
- slip-resistant vinyl in all wet areas;
- hard-surfaced, slip-resistant external pathways with unobstructed width of 1 metre;
- additional heating and/or air-conditioning;

- wheelchair re-charging facilities;
- strobe smoke alarms and doorbell;
- installation of ramp (2 steps or less);

5.6 Major modifications which SouthEast is unlikely to permit unless there is a scheduled major upgrade:

- bathroom/toilet modifications/alterations which may include: -
- replacement of bath with stepless shower;
- lowering of hand basin, benches and shelves;
- replacement and relocation of toilet bowl and cistern;
- structural reinforcement in bathroom to allow for installation of hoist;
- kitchen modifications/alterations which may include lowering of all benches,
 cupboards, shelves; sink; replacement and relocation of stove laundry
 modifications/alterations which may include: lowering of trough, shelving and benches;
- door widening; refitting/replacement of doors and substantial ramping (3 or more steps)

Disability modifications cannot occur without the written approval of SouthEast.

5.7 All new properties developed and/or built by or for SouthEast will be based on the following standard requirements:

- Reinforced wall framing in bathrooms to allow future installation of grab rails.
 Additional noggins to be installed 900mm above FFL around WC and shower.
- Shower door frame to have no bottom rail (threshold less than 5mm in height or bevelled edges) and adjustable/detachable hand held shower rose.

- Internal doorways on the entrance level having a minimum clear opening of 820mm (i.e. an 870 door leaf for hinged doors, also check sliding doors) and minimum corridors of 1000mm or wider clear of fixtures.
- A power point within 300mm of the front of the bench which is adjacent to the cook top.
- Door handles to be lever style and tap hardware to be lever or flick mixer style.
- Light switches to be located near doorways at a height between 900mm and 1100mm.